


- [利点]
- ・密集の度合いが、簡単にわかる
 - ・外れ値を表示する機能を持っている。




①データを縦に並べアクティブにする

x 軸	計測値
A	80.8
A	62.5
A	120.6
A	99.7
A	140.3
A	140.3
A	73.5
A	76.7
.....	
E	101.8
E	104.9
E	103.6
E	101.7
E	106.6
E	103.1
E	101.9





②挿入→縦棒→その他の縦棒グラフ




③箱ひげ図 クリックしてOK


Excelの箱ひげ図作成手順




④グラフの体裁整える



真度と $\pm 3\sigma$



箱ひげ図



外れ値